

**Sea-Bird Electronics, Inc.**

13431 NE 20th Street
Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

Phone

+1-425-643-9866

www.seabird.com

SERVICE REPORT**Service Request****1005519143****Date**

01-DEC-2023

Sales Order

320764317

CUSTOMER INFORMATION

Name: NOAA - WESTERN ACQUISITION DIVISION

Account : 40355945

DAVID MUNRO

DAVID.MUNRO@NOAA.GOV

303-497-5765

PO Number:

WARRANTY

Bill To Address

NOAA - WESTERN ACQUISITION DIVISION

325 BROADWAY

BOULDER,CO,80305,US

Ship To Address

NOAA - WESTERN ACQUISITION DIVISION

325 BROADWAY

BOULDER,CO,80305,US

PRODUCT INFORMATION

Item: ASY-NTR-00085

Item Description: SUNA-V2-10-A, Satlantic

Serial: NTR-1999

Special Notes

Services Requested:

SBS-SVC-SUNA

CUSTOMER NOTES: This sensor is within the warranty, CaseID 00073394

Problems Found:

The windows were found to be scratched.

Services Performed:

Perform initial diagnostic evaluation.

Replaced the lamp and spectrometer windows.

Replaced the lithium back-up battery(s).

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed "POST" cruise calibration.

Item	Item Description	Qty

Unbilled Items

Item	Item Description	Qty
ELE-BAT-00025	BATTERY, LITHIUM COIN 3V 20MM	1
ASY-NTR-00130	SUNA-Ti Lamp Window Assembly: SUNA V2 Ti	1
ASY-NTR-00129	SUNA-Ti Spec Window Assembly: SUNA V2 Ti	1
SBS-SVC-SUNA	Comprehensive service of SUNA V1 and SUNA V2, including all minor and one major repair such as lamp replacement.	1



Sea-Bird Electronics, Inc.

13431 NE 20th Street
Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

Phone

+1-425-643-9866

www.seabird.com

SERVICE REPORT

Service Request

1005519143

Date

01-DEC-2023

Sales Order

320764317