

**Sea-Bird Electronics, Inc.**13431 NE 20th Street
Bellevue, WA 98005 United States

Phone

+1-425-643-9866

www.seabird.com

*(Do Not Send Payments To This Physical Address – See Remit to Information)***SERVICE REPORT****Service Request****1005522495****Date**

10-JAN-2025

Sales Order

321218160

CUSTOMER INFORMATION

Name: NOAA - WESTERN ACQUISITION DIVISION

PO Number:

Account : 40355945

DAVID MUNRO

DAVID.MUNRO@NOAA.GOV

303-497-5765

Bill To Address

NOAA - WESTERN ACQUISITION DIVISION

325 BROADWAY

BOULDER,CO,80305,US

Ship To Address

NOAA - WESTERN ACQUISITION DIVISION

325 BROADWAY

BOULDER,CO,80305,US

PRODUCT INFORMATION**Item:** ASY-NTR-00085**Item Description:** SUNA-V2-10-A, Satlantic**Serial:** NTR-2182**Special Notes**

Problems Found:

The lamp was found to have failed.

Services Performed:

Perform initial diagnostic evaluation.

Installed NEW Lamp assembly.

Performed a "Final" Saltwater Calibration.

Item	Item Description	Qty

Unbilled Items

Item	Item Description	Qty
802746	Tested Deep SUNA Lamp Sub-assembly	1
SBS-SVC-SUNA	COMPREHENSIVE SERVICE/CALIBRATION OF SUNA V2 INCLUDING ALL MINOR AND ONE MAJOR REPAIR SUCH AS LAMP REPLACEMENT.	1